

N/A

CDCV857BGQLR

Part Number:	CDCV857BGQLR
Manufacturer/Brand:	N/A
Product description:	IC 2.5V PLL CLOCK DRVR 56-BGA
Datasheets:	
RoHS Status:	Lead free / RoHS Compliant
Stock Condition:	6241 pcs stock
Ship From:	Hong Kong
Shipment Way:	DHL/Fedex/TNT/UPS/EMS

[REQUEST FOR QUOTATION](#)

Image may be representation. See specifications for product details.

Specifications of CDCV857BGQLR

PART NUMBER	CDCV857BGQLR
MANUFACTURER	N/A
DESCRIPTION	IC 2.5V PLL CLOCK DRVR 56-BGA
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
QUANTITY AVAILABLE	6241 pcs
DATA SHEET	
VOLTAGE - SUPPLY	2.3 V ~ 2.7 V
TYPE	PLL Clock Driver
SUPPLIER DEVICE PACKAGE	56-BGA MICROSTAR JUNIOR (7.0x4.5)
SERIES	-
RATIO - INPUT:OUTPUT	1:10
PACKAGING	Original-Reel®
PACKAGE / CASE	56-VFBGA
PLL	Yes with Bypass
OUTPUT	Clock
OTHER NAMES	296-15358-6
OPERATING TEMPERATURE	0°C ~ 85°C
NUMBER OF CIRCUITS	1
MOUNTING TYPE	Surface Mount
MOISTURE SENSITIVITY LEVEL (MSL)	2 (1 Year)
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
INPUT	Clock
FREQUENCY - MAX	200MHz
DIVIDER/MULTIPLIER	No/No
DIFFERENTIAL - INPUT:OUTPUT	Yes/Yes
BASE PART NUMBER	CDCV857

Related Tags

CDCV857BGQLR	CDCV857BGQLR Distributor	CDCV857BGQLR Supplier
CDCV857BGQLR Price	CDCV857BGQLR Pictures	CDCV857BGQLR Image
CDCV857BGQLR PDF Datasheet	CDCV857BGQLR Download Datasheet	CDCV857BGQLR Datasheet
CDCV857BGQLR Stock	Buy CDCV857BGQLR	Buy CDCV857BGQLR
CDCV857BGQLR	Supplier	Distributor

Related Products

	<p>CDCV857BDGG</p> <p>Manufacturers: N/A Description: IC SSTL-II PLL CLK-DRVR 48-TSSOP In stock: 9137 pcs</p> <p>RFQ</p>		<p>CDCV857BIDGGR</p> <p>Manufacturers: N/A Description: IC SSTL-II PLL CLK-DRVR 48TSSOP In stock: 15960 pcs</p> <p>RFQ</p>
	<p>CDCV857BIDGGG4</p> <p>Manufacturers: N/A Description: IC SSTL-II PLL CLK-DRVR 48-TSSOP In stock: 10624 pcs</p> <p>RFQ</p>		<p>CDCV857BIDGGRG4</p> <p>Manufacturers: N/A Description: IC SSTL-II PLL CLK-DRVR 48TSSOP In stock: 20483 pcs</p> <p>RFQ</p>
	<p>CDCV857ADGGRG4</p> <p>Manufacturers: N/A Description: IC SSTL-II PLL CLK-DRVR 48TSSOP In stock: 23748 pcs</p> <p>RFQ</p>		<p>CDCV857DGGG4</p> <p>Manufacturers: N/A Description: IC SSTL-II PLL CLK-DRVR 48TSSOP In stock: 3721 pcs</p> <p>RFQ</p>
	<p>CDCV857BDGGRG4</p> <p>Manufacturers: N/A Description: IC SSTL-II PLL CLK-DRVR 48TSSOP In stock: 21422 pcs</p> <p>RFQ</p>		<p>CDCV857BDGGG4</p> <p>Manufacturers: N/A Description: IC SSTL-II PLL CLK-DRVR 48TSSOP In stock: 10702 pcs</p> <p>RFQ</p>
	<p>CDCV857BDGGR</p> <p>Manufacturers: N/A Description: IC SSTL-II PLL CLK-DRVR 48TSSOP In stock: 19570 pcs</p> <p>RFQ</p>		<p>CDCV857DGG</p> <p>Manufacturers: N/A Description: IC SSTL-II PLL CLK-DRVR 48TSSOP In stock: 3040 pcs</p> <p>RFQ</p>
	<p>CDCV857AGQLR</p> <p>Manufacturers: N/A Description: IC SSTL-II PLL CLK-DRVR 56-BGA In stock: 4299 pcs</p> <p>RFQ</p>		<p>CDCV857BIDGG</p> <p>Manufacturers: N/A Description: IC SSTL-II PLL CLK-DRVR 48-TSSOP In stock: 10544 pcs</p> <p>RFQ</p>