

N/A

CDCV857BDGGG4

Part Number:	CDCV857BDGGG4
Manufacturer/Brand:	N/A
Product description:	IC SSTL-II PLL CLK-DRVR 48TSSOP
Datasheets:	
RoHS Status:	Lead free / RoHS Compliant
Stock Condition:	10702 pcs stock
Ship From:	Hong Kong
Shipment Way:	DHL/Fedex/TNT/UPS/EMS

[REQUEST FOR QUOTATION](#)

Image may be representation. See specifications for product details.

Specifications of CDCV857BDGGG4

PART NUMBER	CDCV857BDGGG4
MANUFACTURER	N/A
DESCRIPTION	IC SSTL-II PLL CLK-DRVR 48TSSOP
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
QUANTITY AVAILABLE	10702 pcs
DATA SHEET	
VOLTAGE - SUPPLY	2.3 V ~ 2.7 V
TYPE	PLL Clock Driver
SUPPLIER DEVICE PACKAGE	48-TSSOP
SERIES	-
RATIO - INPUT:OUTPUT	1:10
PACKAGING	Tube
PACKAGE / CASE	48-TFSOP (0.240", 6.10mm Width)
PLL	Yes with Bypass
OUTPUT	Clock
OPERATING TEMPERATURE	0°C ~ 85°C
NUMBER OF CIRCUITS	1
MOUNTING TYPE	Surface Mount
MOISTURE SENSITIVITY LEVEL (MSL)	2 (1 Year)
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
INPUT	Clock
FREQUENCY - MAX	200MHz
DIVIDER/MULTIPLIER	No/No
DIFFERENTIAL - INPUT:OUTPUT	Yes/Yes
BASE PART NUMBER	CDCV857

Related Tags

CDCV857BDGGG4	CDCV857BDGGG4 Distributor	CDCV857BDGGG4 Supplier
CDCV857BDGGG4 Price	CDCV857BDGGG4 Pictures	CDCV857BDGGG4 Image
CDCV857BDGGG4 PDF Datasheet	CDCV857BDGGG4 Download Datasheet	CDCV857BDGGG4 Datasheet
CDCV857BDGGG4 Stock	Buy CDCV857BDGGG4	Buy CDCV857BDGGG4
CDCV857BDGGG4	Supplier	Distributor

Related Products

	<p>CDCV857ADGG</p> <p>Manufacturers: N/A Description: IC SSTL-II PLL CLK-DRVR 48-TSSOP In stock: 13432 pcs</p> <p>RFQ</p>		<p>CDCV857BGQLR</p> <p>Manufacturers: N/A Description: IC 2.5V PLL CLOCK DRVR 56-BGA In stock: 6241 pcs</p> <p>RFQ</p>
	<p>CDCV857BDGG</p> <p>Manufacturers: N/A Description: IC SSTL-II PLL CLK-DRVR 48-TSSOP In stock: 9137 pcs</p> <p>RFQ</p>		<p>CDCV857AGQLR</p> <p>Manufacturers: N/A Description: IC SSTL-II PLL CLK-DRVR 56-BGA In stock: 4299 pcs</p> <p>RFQ</p>
	<p>CDCV857ADGGG4</p> <p>Manufacturers: N/A Description: IC SSTL-II PLL CLK-DRVR 48TSSOP In stock: 11078 pcs</p> <p>RFQ</p>		<p>CDCV857BIDGG</p> <p>Manufacturers: N/A Description: IC SSTL-II PLL CLK-DRVR 48-TSSOP In stock: 10544 pcs</p> <p>RFQ</p>
	<p>CDCV857ADGGR</p> <p>Manufacturers: N/A Description: IC SSTL-II PLL CLK-DRVR 48-TSSOP In stock: 10953 pcs</p> <p>RFQ</p>		<p>CDCV857ADGGRG4</p> <p>Manufacturers: N/A Description: IC SSTL-II PLL CLK-DRVR 48TSSOP In stock: 23748 pcs</p> <p>RFQ</p>
	<p>CDCV857BIDGGR</p> <p>Manufacturers: N/A Description: IC SSTL-II PLL CLK-DRVR 48TSSOP In stock: 15960 pcs</p> <p>RFQ</p>		<p>CDCV857BIDGGG4</p> <p>Manufacturers: N/A Description: IC SSTL-II PLL CLK-DRVR 48-TSSOP In stock: 10624 pcs</p> <p>RFQ</p>
	<p>CDCV857BDGGRG4</p> <p>Manufacturers: N/A Description: IC SSTL-II PLL CLK-DRVR 48TSSOP In stock: 21422 pcs</p> <p>RFQ</p>		<p>CDCV857BDGGR</p> <p>Manufacturers: N/A Description: IC SSTL-II PLL CLK-DRVR 48TSSOP In stock: 19570 pcs</p> <p>RFQ</p>