



TDK Corporation

HHM17139B1

Part Number:	HHM17139B1
Manufacturer/Brand:	TDK Corporation
Product description:	BALUN 2.4GHZ-2.5GHZ 50/50 0603
Datasheets:	HHM17139B1.pdf
RoHS Status:	Lead free / RoHS Compliant
Stock Condition:	255709 pcs stock
Ship From:	Hong Kong
Shipment Way:	DHL/Fedex/TNT/UPS/EMS

[REQUEST FOR QUOTATION](#)

Image may be representation. See specifications for product details.

Specifications of HHM17139B1

PART NUMBER	HHM17139B1
MANUFACTURER	TDK Corporation
DESCRIPTION	BALUN 2.4GHZ-2.5GHZ 50/50 0603
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
QUANTITY AVAILABLE	255709 pcs
DATA SHEET	HHM17139B1.pdf
SERIES	-
RETURN LOSS (MIN)	-10dB
PHASE DIFFERENCE	180° ±10°
PACKAGING	Cut Tape (CT)
PACKAGE / CASE	0603 (1608 Metric), 6 PC Pad
OTHER NAMES	445-172633-1
MOUNTING TYPE	Surface Mount
MOISTURE SENSITIVITY LEVEL (MSL)	1 (Unlimited)
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
INSERTION LOSS (MAX)	0.7dB
IMPEDANCE - UNBALANCED/BALANCED	50 / 50 Ohm
FREQUENCY RANGE	2.4GHz ~ 2.5GHz
DETAILED DESCRIPTION	RF Balun 2.4GHz ~ 2.5GHz 50 / 50 Ohm 0603 (1608 Metric), 6 PC Pad

Related Tags

TDK Corporation HHM17139B1	HHM17139B1 Distributor	HHM17139B1 Supplier
HHM17139B1 Price	HHM17139B1 Pictures	HHM17139B1 Image
HHM17139B1 PDF Datasheet	HHM17139B1 Download Datasheet	HHM17139B1 Datasheet
HHM17139B1 Stock	Buy HHM17139B1	Buy TDK Corporation HHM17139B1
TDK Corporation HHM17139B1	TDK Corporation Supplier	TDK Corporation Distributor
TDK Corporation HHM17139B1		

Related Products

<p>HHM17139B2 Manufacturers: TDK Corporation Description: BALUN 2.4GHZ-2.6GHZ 50/50 0603 In stock: 823244 pcs RFQ</p>	<p>HHM1711Q1 Manufacturers: TDK Corporation Description: BALUN 2.3GHZ-3.8GHZ 50/100 0603 In stock: 836875 pcs RFQ</p>
<p>HHM17144A1 Manufacturers: TDK Corporation Description: BALUN 791MHZ-960MHZ 50/100 0603 In stock: 862583 pcs RFQ</p>	<p>HHM17125D1 Manufacturers: TDK Corporation Description: BALUN 2.4GHZ-2.5GHZ 50/50 0603 In stock: 496156 pcs RFQ</p>
<p>HHM1711E1 Manufacturers: TDK Corporation Description: BALUN 2.3GHZ-2.7GHZ 50/100 0603 In stock: 796296 pcs RFQ</p>	<p>HHM17153A2 Manufacturers: TDK Corporation Description: BALUN 698MHZ-894MHZ 50/50 0603 In stock: 387125 pcs RFQ</p>
<p>HHM1715E1 Manufacturers: TDK Corporation Description: BALUN 3.3GHZ-3.9GHZ 50/100 0603 In stock: 54435 pcs RFQ</p>	<p>HHM17146A1 Manufacturers: TDK Corporation Description: BALUN 1.92GHZ-2.17GHZ 50/50 0603 In stock: 920864 pcs RFQ</p>
<p>HHM17152A1 Manufacturers: TDK Corporation Description: BALUN 698MHZ-894MHZ 50/100 0603 In stock: 506941 pcs RFQ</p>	<p>HHM1711D1 Manufacturers: TDK Corporation Description: BALUN 2.4GHZ-2.5GHZ 50/100 0603 In stock: 180690 pcs RFQ</p>
<p>HHM1603A1 Manufacturers: TDK Corporation Description: BALUN 2.3GHZ-2.7GHZ 50/100 4SMD In stock: 120843 pcs RFQ</p>	<p>HHM1710D1 Manufacturers: TDK Corporation Description: BALUN 2.4GHZ-2.5GHZ 50/50 0603 In stock: 460907 pcs RFQ</p>