



TDK Corporation

HHM1506

Part Number:	HHM1506
Manufacturer/Brand:	TDK Corporation
Product description:	BALUN DUAL 50/100 0805
Datasheets:	HHM1506.pdf
RoHS Status:	Lead free / RoHS Compliant
Stock Condition:	853777 pcs stock
Ship From:	Hong Kong
Shipment Way:	DHL/Fedex/TNT/UPS/EMS

[REQUEST FOR QUOTATION](#)

Image may be representation. See specifications for product details.

Specifications of HHM1506

PART NUMBER	HHM1506
MANUFACTURER	TDK Corporation
DESCRIPTION	BALUN DUAL 50/100 0805
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
QUANTITY AVAILABLE	853777 pcs
DATA SHEET	HHM1506.pdf
SERIES	HHM
RETURN LOSS (MIN)	10dB
PHASE DIFFERENCE	180° ±10°
PACKAGING	Tape & Reel (TR)
PACKAGE / CASE	0805 (2012 Metric)
MOUNTING TYPE	Surface Mount
MOISTURE SENSITIVITY LEVEL (MSL)	1 (Unlimited)
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
INSERTION LOSS (MAX)	1.0dB
IMPEDANCE - UNBALANCED/BALANCED	50 / 100 Ohm
FREQUENCY RANGE	1.92GHz ~ 1.98GHz, 2.11GHz ~ 2.17GHz
DETAILED DESCRIPTION	RF Balun 1.92GHz ~ 1.98GHz, 2.11GHz ~ 2.17GHz 50 / 100 Ohm 0805 (2012 Metric)

Related Tags

TDK Corporation HHM1506	HHM1506 Distributor	HHM1506 Supplier
HHM1506 Price	HHM1506 Pictures	HHM1506 Image
HHM1506 PDF Datasheet	HHM1506 Download Datasheet	HHM1506 Datasheet
HHM1506 Stock	Buy HHM1506	Buy TDK Corporation HHM1506
TDK Corporation HHM1506	TDK Corporation Supplier	TDK Corporation Distributor
TDK Corporation HHM1506		

Related Products

<p>HHM15112A1 Manufacturers: TDK Corporation Description: BALUN 900MHZ-2.2GHZ 75/100 0805 In stock: 479672 pcs</p> <p>RFQ</p>	<p>HHM1515B2 Manufacturers: TDK Corporation Description: BALUN 880MHZ-960MHZ 50/200 0805 In stock: 824238 pcs</p> <p>RFQ</p>
<p>HHM-CU Manufacturers: Bussmann (Eaton) Description: FUSE HOLDR BLADE 32V 24A IN LINE In stock: 10229 pcs</p> <p>RFQ</p>	<p>HHM1520A2 Manufacturers: TDK Corporation Description: BALUN 2.3GHZ-2.5GHZ 50/100 0805 In stock: 227929 pcs</p> <p>RFQ</p>
<p>HHM1517 Manufacturers: TDK Corporation Description: BALUN 2.4GHZ-2.5GHZ 50/50 0805 In stock: 821754 pcs</p> <p>RFQ</p>	<p>HHM1517A2 Manufacturers: TDK Corporation Description: BALUN 2.3GHZ-2.5GHZ 50/50 0805 In stock: 205634 pcs</p> <p>RFQ</p>
<p>HHM1518A3 Manufacturers: TDK Corporation Description: BALUN 1.71-1.99GHZ 50/150 0805 In stock: 147339 pcs</p> <p>RFQ</p>	<p>HHM Manufacturers: Bussmann (Eaton) Description: FUSE HOLDR BLADE 32V 24A IN LINE In stock: 10238 pcs</p> <p>RFQ</p>
<p>HHM1516 Manufacturers: TDK Corporation Description: BALUN 1.71-1.99GHZ 50/200 0805 In stock: 787153 pcs</p> <p>RFQ</p>	<p>HHM-BLUE Manufacturers: Bussmann (Eaton) Description: FUSE HOLDR BLADE 32V 24A IN LINE In stock: 24121 pcs</p> <p>RFQ</p>
<p>HHM1521 Manufacturers: TDK Corporation Description: BALUN 2.4GHZ-2.5GHZ 50/200 0805 In stock: 671305 pcs</p> <p>RFQ</p>	<p>HHM1520 Manufacturers: TDK Corporation Description: BALUN 2.4GHZ-2.5GHZ 50/100 0805 In stock: 867237 pcs</p> <p>RFQ</p>

