

NXP Semiconductors / Freescale

MC100ES6139DT

Part Number:	MC100ES6139DT
Manufacturer/Brand:	NXP Semiconductors / Freescale
Product description:	IC CLOCK GENERATION CHIP 20TSSOP
Datasheets:	
RoHS Status:	Contains lead / RoHS non-compliant
Stock Condition:	3635 pcs stock
Ship From:	Hong Kong
Shipment Way:	DHL/Fedex/TNT/UPS/EMS

[REQUEST FOR QUOTATION](#)

Specifications of MC100ES6139DT

PART NUMBER	MC100ES6139DT
MANUFACTURER	NXP Semiconductors / Freescale
DESCRIPTION	IC CLOCK GENERATION CHIP 20TSSOP
LEAD FREE STATUS / ROHS STATUS	Contains lead / RoHS non-compliant
QUANTITY AVAILABLE	3635 pcs
DATA SHEET	
VOLTAGE - SUPPLY	3.135 V ~ 3.8 V
TYPE	Clock Generator
SUPPLIER DEVICE PACKAGE	20-TSSOP
SERIES	100ES
RATIO - INPUT:OUTPUT	1:4
PACKAGING	Tube
PACKAGE / CASE	20-TSSOP (0.173", 4.40mm Width)
PLL	Yes
OUTPUT	ECL
OPERATING TEMPERATURE	-40°C ~ 85°C
NUMBER OF CIRCUITS	1
MOUNTING TYPE	Surface Mount
MOISTURE SENSITIVITY LEVEL (MSL)	1 (Unlimited)
LEAD FREE STATUS / ROHS STATUS	Contains lead / RoHS non-compliant
INPUT	ECL, HSTL, LVDS, PECL
FREQUENCY - MAX	1GHz
DIVIDER/MULTIPLIER	Yes/No
DIFFERENTIAL - INPUT:OUTPUT	Yes/Yes
BASE PART NUMBER	MC100ES6139

Related Tags

MC100ES6139DT	MC100ES6139DT Distributor	MC100ES6139DT Supplier
MC100ES6139DT Price	MC100ES6139DT Pictures	MC100ES6139DT Image
MC100ES6139DT PDF Datasheet	MC100ES6139DT Download Datasheet	MC100ES6139DT Datasheet
MC100ES6139DT Stock	Buy MC100ES6139DT	Buy MC100ES6139DT
MC100ES6139DT	Supplier	Distributor

Related Products

	<p>MC100ES6210FA</p> <p>Manufacturers: NXP Description: IC CLK BUFFER 1:5 3GHZ 32LQFP In stock: 5295 pcs</p> <p>RFQ</p>		<p>MC100ES6139EJ</p> <p>Manufacturers: IDT (Integrated Device Technology) Description: IC CLOCK GENERATION CHIP 20TSSOP In stock: 10815 pcs</p> <p>RFQ</p>
	<p>MC100ES6111FAR2</p> <p>Manufacturers: NXP Description: IC CLK BUFFER 2:10 2.7GHZ 32LQFP In stock: 4547 pcs</p> <p>RFQ</p>		<p>MC100ES6139EJR2</p> <p>Manufacturers: IDT (Integrated Device Technology) Description: IC CLOCK GENERATION CHIP 20TSSOP In stock: 12939 pcs</p> <p>RFQ</p>
	<p>MC100ES6210AC</p> <p>Manufacturers: NXP Description: IC CLK BUFFER 1:5 3GHZ 32LQFP In stock: 6518 pcs</p> <p>RFQ</p>		<p>MC100ES6130EJ</p> <p>Manufacturers: IDT (Integrated Device Technology) Description: IC CLK BUFFER 2:4 2GHZ 16TSSOP In stock: 6444 pcs</p> <p>RFQ</p>
	<p>MC100ES6111FA</p> <p>Manufacturers: NXP Description: IC CLK BUFFER 2:10 2.7GHZ 32LQFP In stock: 3514 pcs</p> <p>RFQ</p>		<p>MC100ES6130EJR2</p> <p>Manufacturers: IDT (Integrated Device Technology) Description: IC CLK BUFFER 2:4 2GHZ 16TSSOP In stock: 6029 pcs</p> <p>RFQ</p>
	<p>MC100ES6130DT</p> <p>Manufacturers: NXP Description: IC CLK BUFFER 2:4 2.5GHZ 16TSSOP In stock: 4022 pcs</p> <p>RFQ</p>		<p>MC100ES6210AC</p> <p>Manufacturers: IDT (Integrated Device Technology) Description: IC CLK BUFFER 1:5 3GHZ 32TQFP In stock: 5700 pcs</p> <p>RFQ</p>
	<p>MC100ES6111FA</p> <p>Manufacturers: IDT (Integrated Device Technology) Description: IC CLK BUFFER 2:10 2.7GHZ 32TQFP In stock: 3130 pcs</p> <p>RFQ</p>		<p>MC100ES6210ACR2</p> <p>Manufacturers: IDT (Integrated Device Technology) Description: IC CLK BUFFER 1:5 3GHZ 32TQFP In stock: 4427 pcs</p> <p>RFQ</p>