

N/A



Image may be representation. See specifications for product details.

CDCV857DGGG4

Part Number:	CDCV857DGGG4
Manufacturer/Brand:	N/A
Product description	IC SSTL-II PLL CLK-DRVR 48TSSOP
Datasheets:	
RoHs Status	 Lead free / RoHS Compliant
Stock Condition	3721 pcs stock
Ship From	Hong Kong
Shipment Way	DHL/Fedex/TNT/UPS/EMS

REQUEST FOR QUOTATION

Specifications of CDCV857DGGG4

PART NUMBER	CDCV857DGGG4
MANUFACTURER	N/A
DESCRIPTION	IC SSTL-II PLL CLK-DRVR 48TSSOP
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
QUANTITY AVAILABLE	3721 pcs
DATA SHEET	
VOLTAGE - SUPPLY	2.3 V ~ 2.7 V
TYPE	PLL Clock Driver
SUPPLIER DEVICE PACKAGE	48-TSSOP
SERIES	-
RATIO - INPUT:OUTPUT	1:10
PACKAGING	Tube
PACKAGE / CASE	48-TFSOP (0.240", 6.10mm Width)
PLL	Yes with Bypass
OUTPUT	Clock
OPERATING TEMPERATURE	0°C ~ 85°C
NUMBER OF CIRCUITS	1
MOUNTING TYPE	Surface Mount
MOISTURE SENSITIVITY LEVEL (MSL)	2 (1 Year)
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
INPUT	Clock
FREQUENCY - MAX	200MHz
DIVIDER/MULTIPLIER	No/No
DIFFERENTIAL - INPUT:OUTPUT	Yes/Yes
BASE PART NUMBER	CDCV857

Related Tags

CDCV857DGGG4	CDCV857DGGG4 Distributor	CDCV857DGGG4 Supplier
CDCV857DGGG4 Price	CDCV857DGGG4 Pictures	CDCV857DGGG4 Image
CDCV857DGGG4 PDF Datasheet	CDCV857DGGG4 Download Datasheet	CDCV857DGGG4 Datasheet
CDCV857DGGG4 Stock	Buy CDCV857DGGG4	Buy CDCV857DGGG4
CDCV857DGGG4	Supplier	Distributor

Related Products

	CDCV857BIDGGR Manufacturers: N/A Description: IC SSTL-II PLL CLK-DRVR 48TSSOP In stock: 15960 pcs RFQ		CDCV857BGQLR Manufacturers: N/A Description: IC 2.5V PLL CLOCK DRVR 56-BGA In stock: 6241 pcs RFQ
	CDCV857DGG Manufacturers: N/A Description: IC SSTL-II PLL CLK-DRVR 48TSSOP In stock: 3040 pcs RFQ		CDCV857BIDGG Manufacturers: N/A Description: IC SSTL-II PLL CLK-DRVR 48-TSSOP In stock: 10544 pcs RFQ
	CDCVF111FN Manufacturers: N/A Description: IC CLK BUFFER 1:9 650MHZ 28PLCC In stock: 5024 pcs RFQ		CDCV857BIDGGG4 Manufacturers: N/A Description: IC SSTL-II PLL CLK-DRVR 48-TSSOP In stock: 10624 pcs RFQ
	CDCV857DGGRG4 Manufacturers: N/A Description: IC SSTL-II PLL CLK-DRVR 48TSSOP In stock: 3960 pcs RFQ		CDCVF111FNR Manufacturers: N/A Description: IC CLK BUFFER 1:9 650MHZ 28PLCC In stock: 7966 pcs RFQ
	CDCVF111FNRG4 Manufacturers: N/A Description: IC CLK BUFFER 1:9 650MHZ 28PLCC In stock: 6597 pcs RFQ		CDCV857DGGR Manufacturers: N/A Description: IC SSTL-II PLL CLK-DRVR 48-TSSOP In stock: 3143 pcs RFQ
	CDCV857BIDGGRG4 Manufacturers: N/A Description: IC SSTL-II PLL CLK-DRVR 48TSSOP In stock: 20483 pcs RFQ		CDCVF111FNG4 Manufacturers: N/A Description: IC CLK BUFFER 1:9 650MHZ 28PLCC In stock: 5342 pcs RFQ

