

N/A

CDCV857ADGGG4

Part Number:	CDCV857ADGGG4
Manufacturer/Brand:	N/A
Product description:	IC SSTL-II PLL CLK-DRVR 48TSSOP
Datasheets:	
RoHS Status:	Lead free / RoHS Compliant
Stock Condition:	11078 pcs stock
Ship From:	Hong Kong
Shipment Way:	DHL/Fedex/TNT/UPS/EMS

[REQUEST FOR QUOTATION](#)

Image may be representation. See specifications for product details.

Specifications of CDCV857ADGGG4

PART NUMBER	CDCV857ADGGG4
MANUFACTURER	N/A
DESCRIPTION	IC SSTL-II PLL CLK-DRVR 48TSSOP
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
QUANTITY AVAILABLE	11078 pcs
DATA SHEET	
VOLTAGE - SUPPLY	2.3 V ~ 2.7 V
TYPE	PLL Clock Driver
SUPPLIER DEVICE PACKAGE	48-TSSOP
SERIES	-
RATIO - INPUT:OUTPUT	1:10
PACKAGING	Tube
PACKAGE / CASE	48-TFSOP (0.240", 6.10mm Width)
PLL	Yes with Bypass
OUTPUT	Clock
OPERATING TEMPERATURE	0°C ~ 85°C
NUMBER OF CIRCUITS	1
MOUNTING TYPE	Surface Mount
MOISTURE SENSITIVITY LEVEL (MSL)	2 (1 Year)
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
INPUT	Clock
FREQUENCY - MAX	180MHz
DIVIDER/MULTIPLIER	No/No
DIFFERENTIAL - INPUT:OUTPUT	Yes/Yes
BASE PART NUMBER	CDCV857

Related Tags

CDCV857ADGGG4	CDCV857ADGGG4 Distributor	CDCV857ADGGG4 Supplier
CDCV857ADGGG4 Price	CDCV857ADGGG4 Pictures	CDCV857ADGGG4 Image
CDCV857ADGGG4 PDF Datasheet	CDCV857ADGGG4 Download Datasheet	CDCV857ADGGG4 Datasheet
CDCV857ADGGG4 Stock	Buy CDCV857ADGGG4	Buy CDCV857ADGGG4
CDCV857ADGGG4	Supplier	Distributor

Related Products

	<p>CDCV857ADGGG4 Manufacturers: N/A Description: IC SSTL-II PLL CLK-DRVR 48-TSSOP In stock: 13432 pcs</p> <p>RFQ</p>		<p>CDCV857ADGGG4 Manufacturers: N/A Description: IC SSTL-II PLL CLK-DRVR 48TSSOP In stock: 23748 pcs</p> <p>RFQ</p>
	<p>CDCV855PWG4 Manufacturers: N/A Description: IC PLL CLOCK DRVR 2.5V 28TSSOP In stock: 38467 pcs</p> <p>RFQ</p>		<p>CDCV857BDGGG4 Manufacturers: N/A Description: IC SSTL-II PLL CLK-DRVR 48TSSOP In stock: 9137 pcs</p> <p>RFQ</p>
	<p>CDCV857AGQLR Manufacturers: N/A Description: IC SSTL-II PLL CLK-DRVR 56-BGA In stock: 4299 pcs</p> <p>RFQ</p>		<p>CDCV855PWR Manufacturers: N/A Description: IC 1:4 DDR PLL CLK-DRVR 28-TSSOP In stock: 29422 pcs</p> <p>RFQ</p>
	<p>CDCV855IPWRG4 Manufacturers: N/A Description: IC PLL CLOCK DRVR 2.5V 28TSSOP In stock: 46293 pcs</p> <p>RFQ</p>		<p>CDCV857BDGGR Manufacturers: N/A Description: IC SSTL-II PLL CLK-DRVR 48TSSOP In stock: 19570 pcs</p> <p>RFQ</p>
	<p>CDCV857ADGGR Manufacturers: N/A Description: IC SSTL-II PLL CLK-DRVR 48-TSSOP In stock: 10953 pcs</p> <p>RFQ</p>		<p>CDCV855PWG4 Manufacturers: N/A Description: IC PLL CLOCK DRVR 2.5V 28TSSOP In stock: 65587 pcs</p> <p>RFQ</p>
	<p>CDCV857BDGGG4 Manufacturers: N/A Description: IC SSTL-II PLL CLK-DRVR 48TSSOP In stock: 10702 pcs</p> <p>RFQ</p>		<p>CDCV855PW Manufacturers: N/A Description: IC 1:4 DDR PLL CLK-DRVR 28-TSSOP In stock: 37488 pcs</p> <p>RFQ</p>