

N/A

### CDCLVP111RHBR

Part Number:	CDCLVP111RHBR
Manufacturer/Brand:	N/A
Product description:	IC CLK BUFFER 2:10 3.5GHZ 32QFN
Datasheets:	
RoHS Status:	Lead free / RoHS Compliant
Stock Condition:	7954 pcs stock
Ship From:	Hong Kong
Shipment Way:	DHL/Fedex/TNT/UPS/EMS

[REQUEST FOR QUOTATION](#)

#### Specifications of CDCLVP111RHBR

PART NUMBER	CDCLVP111RHBR
MANUFACTURER	N/A
DESCRIPTION	IC CLK BUFFER 2:10 3.5GHZ 32QFN
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
QUANTITY AVAILABLE	7954 pcs
DATA SHEET	
VOLTAGE - SUPPLY	2.375 V ~ 3.8 V
TYPE	Fanout Buffer (Distribution), Multiplexer
SUPPLIER DEVICE PACKAGE	32-VQFN (5x5)
SERIES	-
RATIO - INPUT:OUTPUT	2:10
PACKAGING	Cut Tape (CT)
PACKAGE / CASE	32-VFQFN Exposed Pad
OUTPUT	LVPECL
OTHER NAMES	296-24236-1
OPERATING TEMPERATURE	-40°C ~ 85°C
NUMBER OF CIRCUITS	1
MOUNTING TYPE	Surface Mount
MOISTURE SENSITIVITY LEVEL (MSL)	2 (1 Year)
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
INPUT	CML, LVDS, LVPECL, SSTL
FREQUENCY - MAX	3.5GHz
DIFFERENTIAL - INPUT:OUTPUT	Yes/Yes
DETAILED DESCRIPTION	Clock Fanout Buffer (Distribution), Multiplexer IC 2:10 3.5GHz 32-VFQFN Exposed Pad
BASE PART NUMBER	CDCLVP111

#### Related Tags

<a href="#">CDCLVP111RHBR</a>	<a href="#">CDCLVP111RHBR Distributor</a>	<a href="#">CDCLVP111RHBR Supplier</a>
<a href="#">CDCLVP111RHBR Price</a>	<a href="#">CDCLVP111RHBR Pictures</a>	<a href="#">CDCLVP111RHBR Image</a>
<a href="#">CDCLVP111RHBR PDF Datasheet</a>	<a href="#">CDCLVP111RHBR Download Datasheet</a>	<a href="#">CDCLVP111RHBR Datasheet</a>
<a href="#">CDCLVP111RHBR Stock</a>	<a href="#">Buy CDCLVP111RHBR</a>	<a href="#">Buy CDCLVP111RHBR</a>
<a href="#">CDCLVP111RHBR</a>	<a href="#">Supplier</a>	<a href="#">Distributor</a>

#### Related Products

	<p><b>CDCLVP110VFRG4</b></p> <p>Manufacturers: N/A Description: IC CLK BUFFER 2:10 3.5GHZ 32LQFP In stock: 15445 pcs</p> <p><a href="#">RFQ</a></p>		<p><b>CDCLVP111MVFREP</b></p> <p>Manufacturers: N/A Description: IC CLOCK BUFFER MUX 2:10 32LQFP In stock: 4577 pcs</p> <p><a href="#">RFQ</a></p>
	<p><b>CDCLVP111VFR</b></p> <p>Manufacturers: N/A Description: IC CLK BUFFER 2:10 3.5GHZ 32LQFP In stock: 14177 pcs</p> <p><a href="#">RFQ</a></p>		<p><b>CDCLVP110MVFRG4</b></p> <p>Manufacturers: N/A Description: IC CLK BUFFER 2:10 3.5GHZ 32LQFP In stock: 11462 pcs</p> <p><a href="#">RFQ</a></p>
	<p><b>CDCLVP110VFG4</b></p> <p>Manufacturers: N/A Description: IC CLK BUFFER 2:10 3.5GHZ 32LQFP In stock: 11455 pcs</p> <p><a href="#">RFQ</a></p>		<p><b>CDCLVP1204RGTT</b></p> <p>Manufacturers: N/A Description: IC CLK BUFFER 2:4 2GHZ 16QFN In stock: 12477 pcs</p> <p><a href="#">RFQ</a></p>
	<p><b>CDCLVP110VFR</b></p> <p>Manufacturers: N/A Description: IC CLK BUFFER 2:10 3.5GHZ 32LQFP In stock: 14446 pcs</p> <p><a href="#">RFQ</a></p>		<p><b>CDCLVP110VF</b></p> <p>Manufacturers: N/A Description: IC CLK BUFFER 2:10 3.5GHZ 32LQFP In stock: 7934 pcs</p> <p><a href="#">RFQ</a></p>
	<p><b>CDCLVP1204RGTR</b></p> <p>Manufacturers: N/A Description: IC CLK BUFFER 2:4 2GHZ 16QFN In stock: 28155 pcs</p> <p><a href="#">RFQ</a></p>		<p><b>CDCLVP1204EVM</b></p> <p>Manufacturers: N/A Description: EVAL MODULE FOR CDCLVP1204 In stock: 587 pcs</p> <p><a href="#">RFQ</a></p>
	<p><b>CDCLVP111VF</b></p> <p>Manufacturers: N/A Description: IC CLK BUFFER 2:10 3.5GHZ 32LQFP In stock: 9064 pcs</p> <p><a href="#">RFQ</a></p>		<p><b>CDCLVP111RHBT</b></p> <p>Manufacturers: N/A Description: IC CLK BUFFER 2:10 3.5GHZ 32QFN In stock: 12166 pcs</p> <p><a href="#">RFQ</a></p>