

N/A

CDCV857BIDGG

Part Number: CDCV857BIDGG
 Manufacturer/Brand: N/A
 Product description: IC SSTL-II PLL CLK-DRVR 48-TSSOP
 Datasheets:
 RoHS Status: Lead free / RoHS Compliant
 Stock Condition: 10544 pcs stock
 Ship From: Hong Kong
 Shipment Way: DHL/Fedex/TNT/UPS/EMS

[REQUEST FOR QUOTATION](#)

Specifications of CDCV857BIDGG

PART NUMBER	CDCV857BIDGG
MANUFACTURER	N/A
DESCRIPTION	IC SSTL-II PLL CLK-DRVR 48-TSSOP
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
QUANTITY AVAILABLE	10544 pcs
DATA SHEET	
VOLTAGE - SUPPLY	2.3 V ~ 2.7 V
TYPE	PLL Clock Driver
SUPPLIER DEVICE PACKAGE	48-TSSOP
SERIES	-
RATIO - INPUT:OUTPUT	1:10
PACKAGING	Tube
PACKAGE / CASE	48-TFSOP (0.240", 6.10mm Width)
PLL	Yes with Bypass
OUTPUT	Clock
OTHER NAMES	296-13857-5
OPERATING TEMPERATURE	-40°C ~ 85°C
NUMBER OF CIRCUITS	1
MOUNTING TYPE	Surface Mount
MOISTURE SENSITIVITY LEVEL (MSL)	2 (1 Year)
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
INPUT	Clock
FREQUENCY - MAX	200MHz
DIVIDER/MULTIPLIER	No/No
DIFFERENTIAL - INPUT:OUTPUT	Yes/Yes
BASE PART NUMBER	CDCV857

Related Tags

CDCV857BIDGG	CDCV857BIDGG Distributor	CDCV857BIDGG Supplier
CDCV857BIDGG Price	CDCV857BIDGG Pictures	CDCV857BIDGG Image
CDCV857BIDGG PDF Datasheet	CDCV857BIDGG Download Datasheet	CDCV857BIDGG Datasheet
CDCV857BIDGG Stock	Buy CDCV857BIDGG	Buy CDCV857BIDGG
CDCV857BIDGG	Supplier	Distributor

Related Products

	<p>CDCV857AGQLR Manufacturers: N/A Description: IC SSTL-II PLL CLK-DRVR 56-BGA In stock: 4299 pcs</p> <p>RFQ</p>		<p>CDCV857BIDGGRG4 Manufacturers: N/A Description: IC SSTL-II PLL CLK-DRVR 48TSSOP In stock: 20483 pcs</p> <p>RFQ</p>
	<p>CDCV857DGGG4 Manufacturers: N/A Description: IC SSTL-II PLL CLK-DRVR 48TSSOP In stock: 3721 pcs</p> <p>RFQ</p>		<p>CDCV857BDGGRG4 Manufacturers: N/A Description: IC SSTL-II PLL CLK-DRVR 48TSSOP In stock: 21422 pcs</p> <p>RFQ</p>
	<p>CDCV857BDGG Manufacturers: N/A Description: IC SSTL-II PLL CLK-DRVR 48-TSSOP In stock: 9137 pcs</p> <p>RFQ</p>		<p>CDCV857BGQLR Manufacturers: N/A Description: IC 2.5V PLL CLOCK DRVR 56-BGA In stock: 6241 pcs</p> <p>RFQ</p>
	<p>CDCV857BIDGGG4 Manufacturers: N/A Description: IC SSTL-II PLL CLK-DRVR 48-TSSOP In stock: 10624 pcs</p> <p>RFQ</p>		<p>CDCV857DGG Manufacturers: N/A Description: IC SSTL-II PLL CLK-DRVR 48TSSOP In stock: 3040 pcs</p> <p>RFQ</p>
	<p>CDCV857BDGGG4 Manufacturers: N/A Description: IC SSTL-II PLL CLK-DRVR 48TSSOP In stock: 10702 pcs</p> <p>RFQ</p>		<p>CDCV857DGGR Manufacturers: N/A Description: IC SSTL-II PLL CLK-DRVR 48-TSSOP In stock: 3143 pcs</p> <p>RFQ</p>
	<p>CDCV857BDGGR Manufacturers: N/A Description: IC SSTL-II PLL CLK-DRVR 48TSSOP In stock: 19570 pcs</p> <p>RFQ</p>		<p>CDCV857BIDGGR Manufacturers: N/A Description: IC SSTL-II PLL CLK-DRVR 48TSSOP In stock: 15960 pcs</p> <p>RFQ</p>