

N/A

### CDCS504TPWRQ1

Part Number:	CDCS504TPWRQ1
Manufacturer/Brand:	N/A
Product description:	CLOCK FREQUENCY MULTIPLIER
Datasheets:	
RoHS Status:	Lead free / RoHS Compliant
Stock Condition:	68058 pcs stock
Ship From:	Hong Kong
Shipment Way:	DHL/Fedex/TNT/UPS/EMS

[REQUEST FOR QUOTATION](#)

Image may be representation. See specifications for product details.

#### Specifications of CDCS504TPWRQ1

PART NUMBER	CDCS504TPWRQ1
MANUFACTURER	N/A
DESCRIPTION	CLOCK FREQUENCY MULTIPLIER
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
QUANTITY AVAILABLE	68058 pcs
DATA SHEET	
VOLTAGE - SUPPLY	3 V ~ 3.6 V
TYPE	Multiplier
SUPPLIER DEVICE PACKAGE	8-TSSOP
SERIES	Automotive, AEC-Q100
RATIO - INPUT:OUTPUT	1:1
PACKAGING	Cut Tape (CT)
PACKAGE / CASE	8-TSSOP (0.173", 4.40mm Width)
OUTPUT	LVC MOS
OTHER NAMES	296-49596-1
OPERATING TEMPERATURE	-40°C ~ 105°C
NUMBER OF CIRCUITS	1
MOUNTING TYPE	Surface Mount
MOISTURE SENSITIVITY LEVEL (MSL)	3 (168 Hours)
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
INPUT	LVC MOS
FREQUENCY - MAX	108MHz
DIFFERENTIAL - INPUT:OUTPUT	No/No
DETAILED DESCRIPTION	Clock Multiplier IC 1:1 108MHz 8-TSSOP (0.173", 4.40mm Width)

#### Related Tags

<a href="#">CDCS504TPWRQ1</a>	<a href="#">CDCS504TPWRQ1 Distributor</a>	<a href="#">CDCS504TPWRQ1 Supplier</a>
<a href="#">CDCS504TPWRQ1 Price</a>	<a href="#">CDCS504TPWRQ1 Pictures</a>	<a href="#">CDCS504TPWRQ1 Image</a>
<a href="#">CDCS504TPWRQ1 PDF Datasheet</a>	<a href="#">CDCS504TPWRQ1 Download Datasheet</a>	<a href="#">CDCS504TPWRQ1 Datasheet</a>
<a href="#">CDCS504TPWRQ1 Stock</a>	<a href="#">Buy CDCS504TPWRQ1</a>	<a href="#">Buy CDCS504TPWRQ1</a>
<a href="#">CDCS504TPWRQ1</a>	<a href="#">Supplier</a>	<a href="#">Distributor</a>

#### Related Products

<p><b>CDCU877ARHARG4</b> Manufacturers: N/A Description: IC PLL CLOCK DRIVER 1.8V 40VQFN In stock: 25486 pcs</p> <p><a href="#">RFQ</a></p>	<p><b>CDCU877AGQLT</b> Manufacturers: N/A Description: IC PLL CLOCK DRIVER 1.8V 52-BGA In stock: 2999 pcs</p> <p><a href="#">RFQ</a></p>
<p><b>CDCS502PWR</b> Manufacturers: N/A Description: IC OSC CLOCK GENERATOR 8-TSSOP In stock: 89793 pcs</p> <p><a href="#">RFQ</a></p>	<p><b>CDCS503TPWRQ1</b> Manufacturers: N/A Description: IC CLK BUFFER 1:1 108MHZ 8TSSOP In stock: 132674 pcs</p> <p><a href="#">RFQ</a></p>
<p><b>CDCS502PERF-EVM</b> Manufacturers: N/A Description: EVAL PERFORMANCE MOD FOR CDCS502 In stock: 1051 pcs</p> <p><a href="#">RFQ</a></p>	<p><b>CDCS502PW</b> Manufacturers: N/A Description: IC OSC CLOCK GENERATOR 8-TSSOP In stock: 39244 pcs</p> <p><a href="#">RFQ</a></p>
<p><b>CDCU2A877ZQLT</b> Manufacturers: N/A Description: IC PLL CLOCK DRIVER 1.8V 52-BGA In stock: 15289 pcs</p> <p><a href="#">RFQ</a></p>	<p><b>CDCU877ARHAR</b> Manufacturers: N/A Description: IC PLL CLOCK DRIVER 1.8V 40VQFN In stock: 20815 pcs</p> <p><a href="#">RFQ</a></p>
<p><b>CDCU877AGQLR</b> Manufacturers: N/A Description: IC PLL CLOCK DRIVER 1.8V 52-BGA In stock: 6514 pcs</p> <p><a href="#">RFQ</a></p>	<p><b>CDCS503PWR</b> Manufacturers: N/A Description: IC CLK BUFFER 1:1 108MHZ 8TSSOP In stock: 68875 pcs</p> <p><a href="#">RFQ</a></p>
<p><b>CDCS503PW</b> Manufacturers: N/A Description: IC CLK BUFFER 1:1 108MHZ 8TSSOP In stock: 116452 pcs</p> <p><a href="#">RFQ</a></p>	<p><b>CDCU2A877ZQLR</b> Manufacturers: N/A Description: IC PLL CLOCK DRIVER 1.8V 52-BGA In stock: 19558 pcs</p> <p><a href="#">RFQ</a></p>