

N/A



Image may be representation. See specifications for product details.

TLV809J25DBZR

Part Number:	TLV809J25DBZR
Manufacturer/Brand:	N/A
Product description	IC VOLT SUPERVISOR 2.25V SOT23-3
Datasheets:	
RoHs Status	 Lead free / RoHS Compliant
Stock Condition	404687 pcs stock
Ship From	Hong Kong
Shipment Way	DHL/Fedex/TNT/UPS/EMS

REQUEST FOR QUOTATION

Specifications of TLV809J25DBZR

PART NUMBER	TLV809J25DBZR
MANUFACTURER	N/A
DESCRIPTION	IC VOLT SUPERVISOR 2.25V SOT23-3
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
QUANTITY AVAILABLE	404687 pcs
DATA SHEET	
VOLTAGE - THRESHOLD	2.25V
TYPE	Simple Reset/Power-On Reset
SUPPLIER DEVICE PACKAGE	SOT-23-3
SERIES	-
RESET TIMEOUT	120 ms Minimum
RESET	Active Low
PACKAGING	Tape & Reel (TR)
PACKAGE / CASE	TO-236-3, SC-59, SOT-23-3
OUTPUT	Push-Pull, Totem Pole
OPERATING TEMPERATURE	-40°C ~ 85°C (TA)
NUMBER OF VOLTAGES MONITORED	1
MOUNTING TYPE	Surface Mount
MOISTURE SENSITIVITY LEVEL (MSL)	1 (Unlimited)
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
DETAILED DESCRIPTION	Supervisor Push-Pull, Totem Pole 1 Channel SOT-23-3
BASE PART NUMBER	TLV809J25

Related Tags

TLV809J25DBZR	TLV809J25DBZR Distributor	TLV809J25DBZR Supplier
TLV809J25DBZR Price	TLV809J25DBZR Pictures	TLV809J25DBZR Image
TLV809J25DBZR PDF Datasheet	TLV809J25DBZR Download Datasheet	TLV809J25DBZR Datasheet
TLV809J25DBZR Stock	Buy TLV809J25DBZR	Buy TLV809J25DBZR
TLV809J25DBZR	Supplier	Distributor

Related Products

	TLV809J25DBVR Manufacturers: N/A Description: IC VOLT SUPERVISOR 2.25V SOT23-3 In stock: 365584 pcs RFQ		TLV809I50DBVT Manufacturers: N/A Description: IC VOLT SUPERVISOR 4.55V SOT23-3 In stock: 228838 pcs RFQ
	TLV809K33DBZR Manufacturers: N/A Description: IC VOLT SUPERVISOR 2.93V SOT23-3 In stock: 140247 pcs RFQ		TLV809J25DBVT Manufacturers: N/A Description: IC VOLT SUPERVISOR 2.25V SOT23-3 In stock: 104662 pcs RFQ
	TLV809I50DBZT Manufacturers: N/A Description: IC VOLT SUPERVISOR 4.55V SOT23-3 In stock: 222034 pcs RFQ		TLV809KEVM-019 Manufacturers: N/A Description: EVAL MODULE FOR TLV809K33 In stock: 4017 pcs RFQ
	TLV809I50DBVR Manufacturers: N/A Description: IC VOLT SUPERVISOR 4.55V SOT23-3 In stock: 123421 pcs RFQ		TLV809J25DBZT Manufacturers: N/A Description: IC VOLT SUPERVISOR 2.25V SOT23-3 In stock: 127686 pcs RFQ
	TLV809I50DBZR Manufacturers: N/A Description: IC VOLT SUPERVISOR 4.55V SOT23-3 In stock: 396340 pcs RFQ		TLV809K33DBVT Manufacturers: N/A Description: IC VOLT SUPERVISOR 2.93V SOT23-3 In stock: 209205 pcs RFQ
	TLV809K33DBVR Manufacturers: N/A Description: IC VOLT SUPERVISOR 2.93V SOT23-3 In stock: 427288 pcs RFQ		TLV809K33DBZT Manufacturers: N/A Description: IC VOLT SUPERVISOR 2.93V SOT23-3 In stock: 113449 pcs RFQ

