



Johanson Technology

2450DM40A1575E

Part Number:	2450DM40A1575E
Manufacturer/Brand:	Johanson Technology
Product description:	RF DIPLEXER 1.575GHZ/2.45GHZ
Datasheets:	
RoHS Status:	Lead free by exemption / RoHS Compliant
Stock Condition:	51325 pcs stock
Ship From:	Hong Kong
Shipment Way:	DHL/Fedex/TNT/UPS/EMS

[REQUEST FOR QUOTATION](#)

Image may be representation. See specifications for product details.

Specifications of 2450DM40A1575E

PART NUMBER	2450DM40A1575E
MANUFACTURER	Johanson Technology
DESCRIPTION	RF DIPLEXER 1.575GHZ/2.45GHZ
LEAD FREE STATUS / ROHS STATUS	Lead free by exemption / RoHS Compliant
QUANTITY AVAILABLE	51325 pcs
DATA SHEET	
SERIES	-
RETURN LOSS (LOW BAND / HIGH BAND)	10dB / 10dB
PACKAGING	Cut Tape (CT)
OTHER NAMES	712-1562-1
MOUNTING TYPE	Surface Mount
MOISTURE SENSITIVITY LEVEL (MSL)	1 (Unlimited)
LOW BAND ATTENUATION (MIN / MAX DB)	50.00dB / -
LEAD FREE STATUS / ROHS STATUS	Lead free by exemption / RoHS Compliant
HIGH BAND ATTENUATION (MIN / MAX DB)	30.00dB / -
FREQUENCY BANDS (LOW / HIGH)	1.574GHz ~ 1.576GHz / 2.4GHz ~ 2.5GHz
DETAILED DESCRIPTION	RF Diplexor 1.574GHz ~ 1.576GHz / 2.4GHz ~ 2.5GHz

Related Tags

Johanson Technology 2450DM40A1575E	2450DM40A1575E Distributor	2450DM40A1575E Supplier
2450DM40A1575E Price	2450DM40A1575E Pictures	2450DM40A1575E Image
2450DM40A1575E PDF Datasheet	2450DM40A1575E Download Datasheet	2450DM40A1575E Datasheet
2450DM40A1575E Stock	Buy 2450DM40A1575E	Buy Johanson Technology 2450DM40A1575E
Johanson Technology 2450DM40A1575E	Johanson Technology Supplier	Johanson Technology Distributor
Johanson Technology 2450DM40A1575E	Johanson 2450DM40A1575E	Johanson Technology Inc. 2450DM40A1575E

Related Products

<p>2450CMG86980002 Manufacturers: Honeywell Sensing and Productivity Solutions Description: MANUAL RESET THERMOSTAT In stock: 5913 pcs</p> <p>RFQ</p>	<p>2450DP15D5400E Manufacturers: Johanson Technology Description: RF DIPLEXER 2.45GHZ/5.4GHZ 0805 In stock: 331084 pcs</p> <p>RFQ</p>
<p>2450DP15E5400E Manufacturers: Johanson Technology Description: RF DIPLEXER 2.45GHZ/5.4GHZ 1206 In stock: 237478 pcs</p> <p>RFQ</p>	<p>2450DP15F5400E Manufacturers: Johanson Technology Description: RF DIPLEXER 2.45GHZ/5.4GHZ 0805 In stock: 3520 pcs</p> <p>RFQ</p>
<p>2450DP15A5512E Manufacturers: Johanson Technology Description: RF DIPLEXER 2.45GHZ/5.51GHZ 0805 In stock: 273914 pcs</p> <p>RFQ</p>	<p>2450CMG82090129 Manufacturers: Honeywell Sensing and Productivity Solutions Description: MANUAL RESET THERMOSTAT In stock: 5789 pcs</p> <p>RFQ</p>
<p>2450CMG81840033 Manufacturers: Honeywell Sensing and Productivity Solutions Description: MANUAL RESET THERMOSTAT In stock: 5347 pcs</p> <p>RFQ</p>	<p>2450DM41A5400 Manufacturers: Johanson Technology Description: RF DIPLEXER MODULE In stock: 6443 pcs</p> <p>RFQ</p>
<p>2450CMG81840032 Manufacturers: Honeywell Sensing and Productivity Solutions Description: MANUAL RESET THERMOSTAT In stock: 3507 pcs</p> <p>RFQ</p>	<p>2450CP05A5400T Manufacturers: Johanson Technology Description: RF DIPLEXER 0202 4 LEAD In stock: 180076 pcs</p> <p>RFQ</p>
<p>2450CMN80821029 Manufacturers: Honeywell Sensing and Productivity Solutions Description: MANUAL RESET THERMOSTAT In stock: 6610 pcs</p> <p>RFQ</p>	<p>2450DP15B5512E Manufacturers: Johanson Technology Description: RF DIPLEXER 2.45GHZ/5.51GHZ 0805 In stock: 6736 pcs</p> <p>RFQ</p>

Copyright © 2020 Reliable Distributor of Electronic Components

E-mail: Info@infinity-electronic.com

Address: 17F, Gaylord Commercial Building, 114-118 Lockhart Road, Wan Chai, Hong Kong

