



2450BL05A0100T

Part Number:	2450BL05A0100T
Manufacturer/Brand:	Johanson Technology
Product description:	BALUN 2.3GHZ-2.69GHZ 50/100 0202
Datasheets:	2450BL05A0100T.pdf
RoHS Status:	Lead free / RoHS Compliant
Stock Condition:	346165 pcs stock
Ship From:	Hong Kong
Shipment Way:	DHL/Fedex/TNT/UPS/EMS

REQUEST FOR QUOTATION

Image may be representation. See specifications for product details.

Specifications of 2450BL05A0100T

PART NUMBER	2450BL05A0100T
MANUFACTURER	Johanson Technology
DESCRIPTION	BALUN 2.3GHZ-2.69GHZ 50/100 0202
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
QUANTITY AVAILABLE	346165 pcs
DATA SHEET	2450BL05A0100T.pdf
SERIES	2450
RETURN LOSS (MIN)	9.5dB
PHASE DIFFERENCE	180° ±10°
PACKAGING	Tape & Reel (TR)
PACKAGE / CASE	0202 (0505 Metric), 4 PC Pad
OTHER NAMES	712-1646-2
MOUNTING TYPE	Surface Mount
MOISTURE SENSITIVITY LEVEL (MSL)	1 (Unlimited)
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
INSERTION LOSS (MAX)	0.55dB
IMPEDANCE - UNBALANCED/BALANCED	50 / 100 Ohm
FREQUENCY RANGE	2.3GHz ~ 2.69GHz
DETAILED DESCRIPTION	RF Balun 2.3GHz ~ 2.69GHz 50 / 100 Ohm 0202 (0505 Metric), 4 PC Pad

Related Tags

Johanson Technology 2450BL05A0100T	2450BL05A0100T Distributor	2450BL05A0100T Supplier
2450BL05A0100T Price	2450BL05A0100T Pictures	2450BL05A0100T Image
2450BL05A0100T PDF Datasheet	2450BL05A0100T Download Datasheet	2450BL05A0100T Datasheet
2450BL05A0100T Stock	Buy 2450BL05A0100T	Buy Johanson Technology 2450BL05A0100T
Johanson Technology 2450BL05A0100T	Johanson Technology Supplier	Johanson Technology Distributor
Johanson Technology 2450BL05A0100T	Johanson 2450BL05A0100T	Johanson Technology Inc. 2450BL05A0100T

Related Products

<p>2450BL07A0050T Manufacturers: Johanson Technology Description: BALUN 2.4GHZ-2.5GHZ 50/50 0402 In stock: 3869 pcs RFQ</p>	<p>2450AT43H0100E Manufacturers: Johanson Technology Description: RF ANT 2.4GHZ CHIP SOLDER SMD In stock: 4372 pcs RFQ</p>
<p>2450AT43B100E Manufacturers: Johanson Technology Description: RF ANT 2.4GHZ CHIP SOLDER SMD In stock: 338380 pcs RFQ</p>	<p>2450AT43F0100E Manufacturers: Johanson Technology Description: RF ANT 2.4GHZ CHIP SOLDER SMD In stock: 112113 pcs RFQ</p>
<p>2450BL14B050T Manufacturers: Johanson Technology Description: BALUN 2.4GHZ-2.5GHZ 50/50 0603 In stock: 2880 pcs RFQ</p>	<p>2450BL14B200T Manufacturers: Johanson Technology Description: BALUN 2.4GHZ-2.5GHZ 50/200 0603 In stock: 4504 pcs RFQ</p>
<p>2450BL14B100T Manufacturers: Johanson Technology Description: BALUN 2.4GHZ-2.5GHZ 50/100 0603 In stock: 2801 pcs RFQ</p>	<p>2450AT45A100E Manufacturers: Johanson Technology Description: RF ANT 2.4GHZ CHIP SOLDER SMD In stock: 194676 pcs RFQ</p>
<p>2450AT44A100E Manufacturers: Johanson Technology Description: RF ANT 2.4GHZ CHIP SOLDER SMD In stock: 3720 pcs RFQ</p>	<p>2450BL14B100 Manufacturers: Johanson Technology Description: BALUN 2.4GHZ-2.5GHZ 50/100 0603 In stock: 6408 pcs RFQ</p>
<p>2450BL07A0100T Manufacturers: Johanson Technology Description: BALUN 2.4GHZ-2.5GHZ 50/100 0402 In stock: 6085 pcs RFQ</p>	<p>2450AT43D100E Manufacturers: Johanson Technology Description: RF ANT 2.4GHZ CHIP SOLDER SMD In stock: 6073 pcs RFQ</p>