




A Renesas Company

Intersil



ISL32498EUIZ-T

Part Number:	ISL32498EUIZ-T
Manufacturer/Brand:	Intersil
Product description	IC TXRX RS485 FAULT PROT 8MSOP
Datasheets:	 ISL32498EUIZ-T.pdf
RoHs Status	 Lead free / RoHS Compliant
Stock Condition	53900 pcs stock
Ship From	Hong Kong
Shipment Way	DHL/Fedex/TNT/UPS/EMS

REQUEST FOR QUOTATION

Specifications of ISL32498EUIZ-T

PART NUMBER	ISL32498EUIZ-T
MANUFACTURER	Intersil
DESCRIPTION	IC TXRX RS485 FAULT PROT 8MSOP
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
QUANTITY AVAILABLE	53900 pcs
DATA SHEET	 ISL32498EUIZ-T.pdf
VOLTAGE - SUPPLY	4.5 V ~ 5.5 V
TYPE	Transceiver
SUPPLIER DEVICE PACKAGE	8-MSOP
SERIES	-
RECEIVER HYSTERESIS	25mV
PROTOCOL	RS422, RS485
PACKAGING	Tape & Reel (TR)
PACKAGE / CASE	8-TSSOP, 8-MSOP (0.118", 3.00mm Width)
OPERATING TEMPERATURE	-40°C ~ 85°C
NUMBER OF DRIVERS/RECEIVERS	1/1
MOUNTING TYPE	Surface Mount
MOISTURE SENSITIVITY LEVEL (MSL)	1 (Unlimited)
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
DUPLEX	Half
DETAILED DESCRIPTION	1/1 Transceiver Half RS422, RS485 8-MSOP
DATA RATE	15Mbps
BASE PART NUMBER	ISL32498E

Related Tags

Intersil ISL32498EUIZ-T	ISL32498EUIZ-T Distributor	ISL32498EUIZ-T Supplier
ISL32498EUIZ-T Price	ISL32498EUIZ-T Pictures	ISL32498EUIZ-T Image
ISL32498EUIZ-T PDF Datasheet	ISL32498EUIZ-T Download Datasheet	ISL32498EUIZ-T Datasheet
ISL32498EUIZ-T Stock	Buy ISL32498EUIZ-T	Buy Intersil ISL32498EUIZ-T
Intersil ISL32498EUIZ-T	Intersil Supplier	Intersil Distributor
Intersil ISL32498EUIZ-T		

Related Products

 A Renesas Company ISL3259EIBZ-T Manufacturers: Intersil Description: IC TXRX ESD 5V RS485/422 8-SOIC In stock: 63344 pcs RFQ	 A Renesas Company ISL3259EIRZ Manufacturers: Intersil Description: IC TXRX ESD 5V RS485/422 10-DFN In stock: 4124 pcs RFQ
 A Renesas Company ISL3259EIBZ Manufacturers: Intersil Description: IC TXRX ESD 5V RS485/422 8-SOIC In stock: 30801 pcs RFQ	 A Renesas Company ISL32498EIBZ-T Manufacturers: Intersil Description: IC TXRX RS485 FAULT PROT 8SOIC In stock: 49116 pcs RFQ
 A Renesas Company ISL32496EUIZ-T Manufacturers: Intersil Description: IC TXRX 5V RS485 RS422 10MSOP In stock: 37710 pcs RFQ	 A Renesas Company ISL32498EIBZ Manufacturers: Intersil Description: IC TXRX RS485 FAULT PROT 8SOIC In stock: 24939 pcs RFQ
 A Renesas Company ISL3259EUIZ Manufacturers: Intersil Description: IC TXRX ESD 5V RS485/422 8-MSOP In stock: 29982 pcs RFQ	 A Renesas Company ISL32498EUIZ Manufacturers: Intersil Description: IC TXRX RS485 FAULT PROT 8MSOP In stock: 49918 pcs RFQ
 A Renesas Company ISL32498EUIZ-T7A Manufacturers: Intersil Description: IC TXRX RS485 FAULT PROT 8MSOP In stock: 35431 pcs RFQ	 A Renesas Company ISL32498EIBZ-T7A Manufacturers: Intersil Description: IC TXRX RS485 FAULT PROT 8SOIC In stock: 33306 pcs RFQ
 A Renesas Company ISL3259EIRZ-T Manufacturers: Intersil Description: IC TXRX ESD 5V RS485/422 10-DFN In stock: 4661 pcs RFQ	 A Renesas Company ISL32496EUIZ-T7A Manufacturers: Intersil Description: IC TXRX 5V RS485 RS422 10MSOP In stock: 33224 pcs RFQ