



X5083V8I-2.7A

Part Number:	X5083V8I-2.7A
Manufacturer/Brand:	Intersil
Product description:	IC SUPERVISOR CPU 8K EE 8-TSSOP
Datasheets:	X5083V8I-2.7A.pdf
RoHs Status:	Contains lead / RoHS non-compliant
Stock Condition:	6455 pcs stock
Ship From:	Hong Kong
Shipment Way:	DHL/Fedex/TNT/UPS/EMS

[REQUEST FOR QUOTATION](#)

Image may be representation. See specifications for product details.

Specifications of X5083V8I-2.7A

PART NUMBER	X5083V8I-2.7A
MANUFACTURER	Intersil
DESCRIPTION	IC SUPERVISOR CPU 8K EE 8-TSSOP
LEAD FREE STATUS / ROHS STATUS	Contains lead / RoHS non-compliant
QUANTITY AVAILABLE	6455 pcs
DATA SHEET	X5083V8I-2.7A.pdf
VOLTAGE - THRESHOLD	2.93V
TYPE	Simple Reset/Power-On Reset
SUPPLIER DEVICE PACKAGE	8-TSSOP
SERIES	-
RESET TIMEOUT	100 ms Minimum
RESET	Active Low
PACKAGING	Tube
PACKAGE / CASE	8-TSSOP (0.173", 4.40mm Width)
OUTPUT	-
OPERATING TEMPERATURE	-40°C ~ 85°C (TA)
NUMBER OF VOLTAGES MONITORED	1
MOUNTING TYPE	Surface Mount
MOISTURE SENSITIVITY LEVEL (MSL)	1 (Unlimited)
LEAD FREE STATUS / ROHS STATUS	Contains lead / RoHS non-compliant
DETAILED DESCRIPTION	Supervisor 1 Channel 8-TSSOP
BASE PART NUMBER	X5083

Related Tags

Intersil X5083V8I-2.7A	X5083V8I-2.7A Distributor	X5083V8I-2.7A Supplier
X5083V8I-2.7A Price	X5083V8I-2.7A Pictures	X5083V8I-2.7A Image
X5083V8I-2.7A PDF Datasheet	X5083V8I-2.7A Download Datasheet	X5083V8I-2.7A Datasheet
X5083V8I-2.7A Stock	Buy X5083V8I-2.7A	Buy Intersil X5083V8I-2.7A
Intersil X5083V8I-2.7A	Intersil Supplier	Intersil Distributor
Intersil X5083V8I-2.7A		

Related Products

<p>X5083S8Z-2.7T1 Manufacturers: Intersil Description: IC SUPERVISOR CPU 8K EE 8-SOIC In stock: 33850 pcs</p> <p>RFQ</p>	<p>X5083V8-4.5A Manufacturers: Intersil Description: IC SUPERVISOR CPU 8K EE 8-TSSOP In stock: 4384 pcs</p> <p>RFQ</p>
<p>X5083V8-2.7 Manufacturers: Intersil Description: IC SUPERVISOR CPU 8K EE 8-TSSOP In stock: 4845 pcs</p> <p>RFQ</p>	<p>X5083V8I-2.7 Manufacturers: Intersil Description: IC SUPERVISOR CPU 8K EE 8-TSSOP In stock: 4739 pcs</p> <p>RFQ</p>
<p>X5083V8I Manufacturers: Intersil Description: IC SUPERVISOR CPU 8K EE 8-TSSOP In stock: 5585 pcs</p> <p>RFQ</p>	<p>X5083S8Z-2.7A Manufacturers: Intersil Description: IC CPU SUPERV 8K EEPROM 8-SOIC In stock: 26483 pcs</p> <p>RFQ</p>
<p>X5083V8IZ-2.7 Manufacturers: Intersil Description: IC SUPERVISOR CPU 8K EE 8-TSSOP In stock: 2777 pcs</p> <p>RFQ</p>	<p>X5083V8 Manufacturers: Intersil Description: IC SUPERVISOR CPU 8K EE 8-TSSOP In stock: 6122 pcs</p> <p>RFQ</p>
<p>X5083V8IZ Manufacturers: Intersil Description: IC CPU SUPERV 8K EEPROM 8-TSSOP In stock: 6756 pcs</p> <p>RFQ</p>	<p>X5083V8-2.7A Manufacturers: Intersil Description: IC SUPERVISOR CPU 8K EE 8-TSSOP In stock: 7089 pcs</p> <p>RFQ</p>
<p>X5083S8Z-4.5A Manufacturers: Intersil Description: IC CPU SUPERV 8K EEPROM 8-SOIC In stock: 25483 pcs</p> <p>RFQ</p>	<p>X5083V8I-4.5A Manufacturers: Intersil Description: IC SUPERVISOR CPU 8K EE 8-TSSOP In stock: 5692 pcs</p> <p>RFQ</p>