

N/A

### LMX2305TMX

Part Number:	LMX2305TMX
Manufacturer/Brand:	N/A
Product description:	IC FREQ SYNTH DUAL 20-TSSOP
Datasheets:	
RoHS Status:	Contains lead / RoHS non-compliant
Stock Condition:	5622 pcs stock
Ship From:	Hong Kong
Shipment Way:	DHL/Fedex/TNT/UPS/EMS

[REQUEST FOR QUOTATION](#)

#### Specifications of LMX2305TMX

PART NUMBER	LMX2305TMX
MANUFACTURER	N/A
DESCRIPTION	IC FREQ SYNTH DUAL 20-TSSOP
LEAD FREE STATUS / ROHS STATUS	Contains lead / RoHS non-compliant
QUANTITY AVAILABLE	5622 pcs
DATA SHEET	
VOLTAGE - SUPPLY	2.65 V ~ 5.5 V
TYPE	PLL Frequency Synthesizer
SUPPLIER DEVICE PACKAGE	20-TSSOP
SERIES	PLLatinum™
RATIO - INPUT:OUTPUT	1:1
PACKAGING	Tape & Reel (TR)
PACKAGE / CASE	20-TSSOP (0.173", 4.40mm Width)
PLL	Yes
OUTPUT	Clock
OTHER NAMES	*LMX2305TMX
OPERATING TEMPERATURE	-40°C ~ 85°C
NUMBER OF CIRCUITS	1
MOUNTING TYPE	Surface Mount
MOISTURE SENSITIVITY LEVEL (MSL)	1 (Unlimited)
LEAD FREE STATUS / ROHS STATUS	Contains lead / RoHS non-compliant
INPUT	Clock
FREQUENCY - MAX	550MHz
DIVIDER/MULTIPLIER	Yes/No
DIFFERENTIAL - INPUT:OUTPUT	Yes/No
BASE PART NUMBER	LMX2305

#### Related Tags

LMX2305TMX	LMX2305TMX Distributor	LMX2305TMX Supplier
LMX2305TMX Price	LMX2305TMX Pictures	LMX2305TMX Image
LMX2305TMX PDF Datasheet	LMX2305TMX Download Datasheet	LMX2305TMX Datasheet
LMX2305TMX Stock	Buy LMX2305TMX	Buy LMX2305TMX
LMX2305TMX	Supplier	Distributor

#### Related Products

<p><b>LMX2216M</b> Manufacturers: N/A Description: IC AMP CELLUL 100MHZ-2GHZ 16SOIC In stock: 6751 pcs</p> <p><a href="#">RFQ</a></p>	<p><b>LMX2311USLDX/NOPB</b> Manufacturers: N/A Description: IC FREQ SYNTH 2.0GHZ 20LAMTCSP In stock: 4215 pcs</p> <p><a href="#">RFQ</a></p>
<p><b>LMX1601TMX/NOPB</b> Manufacturers: N/A Description: IC FREQ SYNTHESIZER DUAL 16TSSOP In stock: 4735 pcs</p> <p><a href="#">RFQ</a></p>	<p><b>LMX2306SLBX/NOPB</b> Manufacturers: N/A Description: IC FREQ SYNTH 16LAMINATE CSP In stock: 3490 pcs</p> <p><a href="#">RFQ</a></p>
<p><b>LMX2310USLDX/NOPB</b> Manufacturers: N/A Description: IC FREQ SYNTH 2.5GHZ 20LAMTCSP In stock: 3480 pcs</p> <p><a href="#">RFQ</a></p>	<p><b>LMX2216MX</b> Manufacturers: N/A Description: IC AMP CELLUL 100MHZ-2GHZ 16SOIC In stock: 5386 pcs</p> <p><a href="#">RFQ</a></p>
<p><b>LMX1602SLBX</b> Manufacturers: N/A Description: IC FREQ SYNTH DL 1.1GHZ 16-LAMIN In stock: 3360 pcs</p> <p><a href="#">RFQ</a></p>	<p><b>LMX2312USLDX/NOPB</b> Manufacturers: N/A Description: IC FREQ SYNTH 1.2GHZ 20LAMTCSP In stock: 3808 pcs</p> <p><a href="#">RFQ</a></p>
<p><b>LMX2306TMX/NOPB</b> Manufacturers: N/A Description: IC FREQ SYNTH LOW PWR 16-TSSOP In stock: 5417 pcs</p> <p><a href="#">RFQ</a></p>	<p><b>LMX1602TM/NOPB</b> Manufacturers: N/A Description: IC PLL DUAL 1.1GHZ 16TSSOP In stock: 5212 pcs</p> <p><a href="#">RFQ</a></p>
<p><b>LMX1602TMX/NOPB</b> Manufacturers: N/A Description: IC FREQ SYNTH DL 1.1GHZ 16-TSSOP In stock: 6883 pcs</p> <p><a href="#">RFQ</a></p>	