



TDK Corporation

HHM1523C1

Part Number:	HHM1523C1
Manufacturer/Brand:	TDK Corporation
Product description:	BALUN 880MHZ-960MHZ 50/100 0805
Datasheets:	HHM1523C1.pdf
RoHS Status:	Lead free / RoHS Compliant
Stock Condition:	54170 pcs stock
Ship From:	Hong Kong
Shipment Way:	DHL/Fedex/TNT/UPS/EMS

[REQUEST FOR QUOTATION](#)

Image may be representation. See specifications for product details.

Specifications of HHM1523C1

PART NUMBER	HHM1523C1
MANUFACTURER	TDK Corporation
DESCRIPTION	BALUN 880MHZ-960MHZ 50/100 0805
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
QUANTITY AVAILABLE	54170 pcs
DATA SHEET	HHM1523C1.pdf
SERIES	HHM
RETURN LOSS (MIN)	10dB
PHASE DIFFERENCE	180° ±10°
PACKAGING	Cut Tape (CT)
PACKAGE / CASE	0805 (2012 Metric)
OTHER NAMES	445-3960-1
MOUNTING TYPE	Surface Mount
MOISTURE SENSITIVITY LEVEL (MSL)	1 (Unlimited)
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
INSERTION LOSS (MAX)	1.1dB
IMPEDANCE - UNBALANCED/BALANCED	50 / 100 Ohm
FREQUENCY RANGE	880MHz ~ 960MHz
DETAILED DESCRIPTION	RF Balun 880MHz ~ 960MHz 50 / 100 Ohm 0805 (2012 Metric)

Related Tags

TDK Corporation HHM1523C1	HHM1523C1 Distributor	HHM1523C1 Supplier
HHM1523C1 Price	HHM1523C1 Pictures	HHM1523C1 Image
HHM1523C1 PDF Datasheet	HHM1523C1 Download Datasheet	HHM1523C1 Datasheet
HHM1523C1 Stock	Buy HHM1523C1	Buy TDK Corporation HHM1523C1
TDK Corporation HHM1523C1	TDK Corporation Supplier	TDK Corporation Distributor
TDK Corporation HHM1523C1		

Related Products

<p>HHM1525 Manufacturers: TDK Corporation Description: BALUN 1.71GHZ-1.99GHZ 50/50 0805 In stock: 532768 pcs RFQ</p>	<p>HHM1524B1 Manufacturers: TDK Corporation Description: BALUN 880MHZ-960MHZ 50/150 0805 In stock: 423494 pcs RFQ</p>
<p>HHM1541E1 Manufacturers: TDK Corporation Description: BALUN 2.3GHZ-2.5GHZ 50/75 0805 In stock: 548409 pcs RFQ</p>	<p>HHM1526 Manufacturers: TDK Corporation Description: BALUN 1.71-1.99GHZ 50/100 0805 In stock: 69461 pcs RFQ</p>
<p>HHM1521 Manufacturers: TDK Corporation Description: BALUN 2.4GHZ-2.5GHZ 50/200 0805 In stock: 671305 pcs RFQ</p>	<p>HHM1522B1 Manufacturers: TDK Corporation Description: BALUN 880MHZ-960MHZ 50/50 0805 In stock: 492262 pcs RFQ</p>
<p>HHM1534 Manufacturers: TDK Corporation Description: BALUN DUAL 50/200 0805 In stock: 205642 pcs RFQ</p>	<p>HHM1523B3 Manufacturers: TDK Corporation Description: BALUN 824MHZ-894MHZ 50/100 0805 In stock: 383181 pcs RFQ</p>
<p>HHM1520 Manufacturers: TDK Corporation Description: BALUN 2.4GHZ-2.5GHZ 50/100 0805 In stock: 867237 pcs RFQ</p>	<p>HHM1520A2 Manufacturers: TDK Corporation Description: BALUN 2.3GHZ-2.5GHZ 50/100 0805 In stock: 227929 pcs RFQ</p>
<p>HHM1522A7 Manufacturers: TDK Corporation Description: BALUN 824MHZ-894MHZ 50/50 0805 In stock: 462635 pcs RFQ</p>	<p>HHM1524B4 Manufacturers: TDK Corporation Description: BALUN 824MHZ-894MHZ 50/150 0805 In stock: 420268 pcs RFQ</p>

